


Forming the aluminum plow front is not difficult, provided that the sequence of operations outlined is followed. The aluminum is very soft and easily marred, so be careful not to stretch it or mar it with fingernails, etc.

The drawing is full size. We suggest that you cut it out and practice on it before working with the aluminum.



If you spoil the plow front, send to Northeastern Scale Models for another at no charge.

Northeastern can also supply the plow front, all formed and trimmed for 50¢, postpaid.